

V paketu ACCLOG V1.23 sta opazeni naslednji nepravili:

- 1.) V Primeru, da uporabnik spoolira datoteko in izda BYE ukaz, ko je v toku izrisovanje za drugega uporabnika, pride do padca operativnega sistema.
Problem se resuje z naslednjo SLP korekcijo:

[11,10]LFDRV.MAC/AU:72./-BF=[11,10]LFDRV.MAC

-2,2

.IDENT /08.1G/

-44

;

;

PV117 -- 20-MAR-81 CONDITIONALY ASSEMBLING FOR ACCOUNTING

;

PV118 -- 20-MAR-81 COUNT PAGE AS SYSTEM OVERHEAD WHEN USER LOGGED ON

-424,,/; PV117/

.IF DF A\$\$LOG

-430,431,/; PV118/

```

MOV    $LFTI,R1      ; GET USER TERMINAL UCB ADDRESS
BEQ    169$          ; EQ - THERE IS NONE.
BIT    #U2.LOG,U.CW2(R1) ; USER LOGGED ON?
BNE    168$          ; NE - NO. PREVENT CRASH
MOV    R1,-(SP)       ; EVERYTHING IS OK
BR    170$           ;
168$: CLR    $LFTI      ; RESET UCB ADDRESS
169$:                   ; REF. LABEL
-466,,/; PV117/

```

PATII .ENDC

←

Popravek se izvaja po naslednji sekvenci:

```

Editira se datoteka LFDRV.CMD z vornjo vsebino.
>SLP @LFDRV
>MAC LPDRV=[1,1]EXEMC/ML,[11,10]RSXMC/PA:1,LFDRV
>LBR [1,24]RSX11M/RF=LFDRV
Generira se novi LFDRV ...
>@[200,200]SGNBLDDRV
Po koncani generaciji ...
>UNL LP:
>LOA LP:
>SET /UIC=[1,54]
>RUN $VMR
ENTER FILENAME: RSX11M
VMR>UNL LP:
VMR>LOA LP:
VMR>Z

```

V pomoznem programu ACCSEQ je napacna konverzija dneva v datumu, ko je zaporedna stevilka dneva < 10. Problem resuje naslednja korekcija:

```
.TITLE ACCSEQ  
.IDENT /02.01/
```

PROBLEM: ACCSEQ conversion utility does not work properly for days < 10. The following patch solve this problem.

PROCEDURE:

```
>LBR ACCSEQ.OLD=[1,24]ACCLOG/EX:ACCSEQ  
>MAC ACCSEQ.POB=ACCSEQ.PAT  
>PAT ACCSEQ.ORJ=ACCSEQ.OLD/CS:147425,ACCSEQ.POB/CS:010045  
>LBR [1,24]ACCLOG/RF/-EP:ACCSEQ.OBJ
```

Rebuild task as follows

```
>TKB  
TKB>[1,54]ACCSEQ=[1,24]ACCLOG/LB:ACCSEQ:ERRMSG
```

/ ENTER OPTIONS:

UNITS=4
STACK=64
//

FV116 -- 6-MAR-81 TIME OF YEAR CONVERSION

```
$PC=,  
+$PC+1774  
CALL PAT1  
+$PC  
PAT1:  
    .PSECT $$$FAT  
    CMP 4(R5),#10.      ; TWO DIGITS FOR DAY?  
    RETURN  
  
.END
```

PROBLEM:

Kako restaurirati datoteku CORIMG-SYS?

REŠENJE:

Ako je datoteka izbrisana potrebno je imati bar još jednu jedinicu diska.

- Alocirati disk za privilegovani terminal. Poželjno je da se radi sa konzole bez ostalih korisnika na sistemu.
- Mount-irati disk sa /UNL opcijom kod MOU komande.
- Proveriti da li postoji CORIMG.SYS. Ako ne postoji proveriti sa VFY pomoćnim programom da li je peti FILE-ID slobodan; oslobođiti ga i prepisati sa drugog diska datoteku CORIMG.SYS.
- Izvršiti sledeće komande:

```
>ASN dev:=SY:  
>RUN $ZAP  
ZAP>[Ø,Ø]ØØØØØØ.DIR/AB  
1Ø2/  
ØØØ:ØØØ1Ø2/ inv-seq-no  
_5  
_X  
>RUN $ZAP  
ZAP>[Ø,Ø]INDEXF.SYS/AB  
_n+4:Ø;ØR  
_Ø,4/  
_n+4:Ø,ØØØØØ4/ inv-seq-no.  
_5  
_Ø,766/  
_n+4:Ø,ØØØ766/ YYYYYYY  
_ZZZZZZ  
_X
```

Sada možemo izvršiti ACS komandu za taj disk.

NAPOMENA:

n je logički blok FILE-HAEDER-a datoteke INDEXF.SYS.

inv-seq-no. je pogrešan SEQ. broj.

ZZZZZZ je nova kontrolna suma i njena vrednost je izračunata po
formuli: ZZZZZZ=YYYYYY-(inv-seq-no. - 5)

YYYYYY je stara kontrolna suma.

Svi pomenuti brojevi su oktalni.

b) Kako se na početku procedura definiše radni UIC za Patch u simbolu "\$PUIC" bilo bi poželjno iz njega izvaditi vrednost za naredbe kao što su:

- TESTFILE SYØ:[Ø,Ø] 001161.DIR; 1
- PIP [0,0] 001161.DIR;1/DE/NM

tako da je samo jedna modifikacija dovoljna u slučaju potrebe, na primer ako želimo istovremeno da radimo dve različite procedure sa više terminala.

5. Radne i zapaljene sa PATCH UTILS

Pošte rada kod instalacije Centračnog, neki korisnici

1. AUTOPATCH.DSK javlja da nije u mogućnosti da odredića instalacione datoteke.

IP - varijabla mora biti implicitno definisana u SP

USCPL.DSK

Na pitanje: "Select your IO Library (BSB,SDQ or DSK)" umesto DSK treba da stoji BSB, inace javlja gresku u izvođenju tret programu.

3. INSYST.DSK

Ne bi trebalo brisati datoteku SY:[1,2]SYST.DSK jer je ona upotrebljavana i sa novijom verzijom DSU 1.2.0. Prethodne promenice joj lese i ostariti korisniku da je obrise tako da

4. Sugestije za poboljšanje rada sa autopatchom
a) Na kraju procedure patchiranju ili instalacije kompjutera, a pre poisanja svih datoteka i direktorija postaviti mrezu "da li je u radu". Tako da je moguce u slajdaju posle, ponavljati funkciju tih mesta preko kojih se mogu pristupiti svim datotekama na trake na disk.

SEKTORU ZA PROIZVODNJO SOFTWARE-a

V ACCLOG V1.23 je opazena napaka pri stetju I/O v slujaju da je traka mountana. Naslednji patch resuje ta problem. Regeneracija sistema ni potrebna, toda potrebno je izvesti ZAP in OBJ patch.

SWR

SK = 22

AG = 26

SPDR =

PPRC+636

BIC

CMP

*TCK(BV,SGD1DV,F111DV,MNT)+(SP) + CLEAR SPARES
#DV,SGD1DV,F111DV,MNT+(SP)+ 1 HAD TAPE

PPRC+700

BIC

CMP

*TCK(BV,DIR1DV,F111DV,MNT)+(SP) + CLEAR SPARES BITS
#DV,DIR1DV,F111DV,MNT+(SP)+ 1 DISK

PPRC+712

ADD

ADC

M+AC,DEK+2(R2) + INCREMENT DISK COUNT
ADC,DEK(R2) + 1 + DON T FORGET COUNT

PPRC+726

ADD

ADC

M+AC,DEK+2(R2) + INCREMENT TAPE COUNT
ADC,DEK(R2) + 1 HIGH PART DEG

END

•TITLE LGSUB
 •IDENT /01.26/

OBJECT PATCH

PROBLEM: QIO'S TO MOUNTED MAGTAFES ARE COUNTED AS DISK I/O.

PROCEDURE:

```
>LBR LGSUB.OLD=[1,24]ACCLOG/EX:LGSUB
>MAC LGSUB.POB=LGSUB.PAT
>PAT LGSUB.OBJ=LGSUB.OLD/CS:015556,LGSUB.POB/CS:030324
>LBR [1,24]ACCLOG/RP=LGSUB/-EP
```

PV115 -- 22-JAN-81 FIX BUG IN MOUNT TAPE I/O COUNT

AC.DSK = 22
 AC.MAG = 26

\$PC=,

.= \$PC+636

BIC *^C<DV.SQD!DV.F11!DV.MNT>,(SP) ; CLEAR IRELEVANT BITS
 CMP *DV.SQD!DV.F11!DV.MNT,(SP)+ ; MAG TAPE?

.= \$PC+700

BIC *^C<DV.DIR!DV.F11!DV.MNT>,(SP) ; CLEAR SPARE BITS
 CMP *DV.DIR!DV.F11!DV.MNT,(SP)+ ; DISK?

.= \$PC+712

ADD #1,AC.DSK+2(R2) ; INCREMENT DISK I/O COUNT
 ADC AC.DSK(R2) ; DON'T FORGET CARRY

.= \$PC+726

ADD #1,AC.MAG+2(R2) ; INCREMENT TAPE I/O COUNT
 ADC AC.MAG(R2) ; HIGH PART ALSO

.END

PROBLEM: QIO'S TO MOUNTED MAGTAPES ARE COUNTED AS DISK I/O

PROCEDURE:

FIND OUT VALUE OF GLOBAL SYMBOL \$ACRES IN [1,34]RSX11M.MAF

\$ACRES = nnn 004622

INVOKE PATCH AS FOLLOWS

004576

>ZAP

ZAP>[1,54]RSX11M.SYS/AB

_2000+nnnn;OR

_0,640/

037767 37737

_0,644/

140010 140040

_0,702/

037736 37767

_0,706/

140041 140010

_0,716/

000030 24

_0,722/

000026 22

_0,732/

000024 30

_0,736/

000022 26

-X



®

INTERNO OBVESTILO

delta računalniški sistemi

ZA: V. Pečar

OD: V. Nonveiller

V VEDNOST: J. Gvardijančić, D. Šnajder

KRAJ IN DATUM: Beograd, 14.09.1981.

Primedbe i zapažanja na PATCH "JUL 81"

Posle rada kod korisnika: Centroslavija, Janko Lisjak, Dunav,

1. AUTOPATCH.CMD javlja grešku u delu "Replace corrected system generation files":

PIP - Version must be explicit or */ SY: [200,200] AP

2. INSCBL.CMD

Na pitanje: "Select your RMS library (RES,SEQ or DSK)" umesto DSK treba da stoji DISK inače javlja grešku prilikom linkovanja test programa.

3. INSDTR.CMD

Ne bi trebalo brisati datoteku SY:[1,2]QUERY.DIC jer je ona upotrebljavana i sa novijom verzijom DTR V 2.0. Eventualno promeniti joj ime i ostaviti korisniku da je obriše ako želi.

4. Sugestije za poboljšanje rada sa autopatchom

- a) Na kraju procedure patchiranja ili instalacije kompjlera, a pre brisanja svih datoteka i direktorija postaviti pitanje "da li je u redu". Tako da je moguće u slučaju greške, ponoviti delove ili celu proceduru bez da se ponovo prepisuje sa trake na disk, a da se ne mora ponoviti prepisivanje datoteka sa trake na disk.

SPOROČILO DECUS O OPAŽANIH RESNIH NAPAKAH V
OPERACIJSKEM SISTEMU VMS 3.1

1. Korupcija strukture diska pri stand-alone BACKUP:
Extension file headers so korumpirani na izvornem disku, če uporabljamo kretnico /RECORD. Zato delajmo brez te kretnice, če pa je škoda že narejena, je treba takoj disk restavrirati, ker save-set ni poškodovan.
2. Padec sistema pri uporabi Remote Terminalov (preko DECneta):
Sistem se dostikrat zruši, če je uporabnik zvezan preko DECneta in nima dovolj velike BYTLM kvote. Zato bo vsem uporabnikom preko DECneta treba zagotoviti dovolj veliko Buffered I/O Byte Count kvoto za njihove največje QIO.

DECUS nič ne pove, če so te napake prisotne tudi pri VMS 3.0, vendar previdnost (predvsem pod tč. 1) najbrž ni odveč.

Davor ŠOŠTARIČ
Davor Šoštarič

Maribor, 16. 2. 1983

```

*****
; AR NO. 790016
; PROBLEM:
; MP (MEMORY PROTECTION) ERROR AND 'IVHF' STATUS COULD OCCUR EVEN
; THOUGH VALID DATA WAS PASSED AS AN ARGUMENT.
; MODULE:
; DATBAS.OBJ

; OPEN DATBAS.PAT
; ENABLE DATA
    .TITLE DATBAS
    .IDENT /020016/
    .PSECT DATBAS
    .MCALL GTSK$$,SVTK$$

; AR #790016      CHECKSUM = 41341

; BASE:
MAXSIZ=1024.
.=BASE+676
    JSR    PC,PA1016
.=BASE+1230
    BEQ    20$  

10$:  MOV   (R0)+,(R1)+  

        CMP   R1,BASE+122
        BHIS  20$  

        SOD   R2,10$  

20$:  CLC
        NOP
        NOP
.=BASE+3474
    JSR    PC,PAR016
    NOP
.=BASE+4132
    JSR    PC,PAC016
    .PSELECT P90016
PAT016: MOV   4(R5),R4
        GTSK$$ #TPARM
        SVTK$$ #SSTRAP,#2
        RTS   PC
PAR016: CMP   BASE+112,#MAXSIZ
        BLUS  10$  


10$:  MOV   #MAXSIZ,BASE+112
        MOV   BASE+112,14(R2)
        RTS   PC
PAC016:
        SVTK$$ TPARM+26,TPARM+30
        CLR   BASE+64
        RTS   PC
MEMPRO: ADD   #6,SP
        MOV   #1,R2
        RTI
SSTRAP: .WURD  0,MEMPRO
TPARM: .BLKW  18.
    .END

; DISABLE DATA
; CLOSE DATBAS.PAT
MAC DATBAS.PBJ=DATBAS.PAT
PAT DATBAS.OBJ=DATBAS.OBJ,DATBAS.PBJ/CS:41341
PIP DATBAS.PBJ;*,DATBAS.PAT;*/DE

```

dela O.K.

6-MAR-82 TAM



računalniški sistemi delta

INTERNO OBVESTILO

glasnik obšte
VSPD

ZA: Viktor Mrak

OD: Vladimir Pečar

V VEDNOST: Vsem delavcem VSPO

KRAJ IN DATUM: Ljubljana, 22.03.1984

PREDMET: Accounting V 2.0

Crash sistema pri delu s QUE MANAGER


Po koncu generacije sistema (pred BOOT-om novega sistema) je treba obvezno
zbrisati FILE [1,7] QUEUE.SYS.

u

Pozdrav,

Vladimir Pečar

Pečar Vladimir



INTERNO OBVESTILO

Objavljeno na deski
13 PO

ZA: Viktor Mrak

OD: Vladimir Pečar

V VEDNOST: Vsem delavcem VSPO

KRAJ IN DATUM: Ljubljana, 22.03.1984

PREDMET: SYSTEM CRASH pri mountu diskete na sistemu DELTA 700/80 SML

Za rešitev tega problema je treba:

- Kreirati SLP File v DXDRV.SLP (glej prilogo)

- obdelati s SLP procesorjem

SLP @ DXDRV.SLP

- asemblerati in linkati driver in loadati.

Pozdrav,

Vladimir Pečar

Pečar Vla. sro



radunalniški sistemi d.o.o.

```
[11,10]DXDRV.MAC;2/-BF/AU:72.=[11,10]DXDRV.MAC;1
\
-2,2
      .IDENT /03.04/
-43
;
;
DRS001 - 22-MAR-84 CORRECT BUG IN POOL DEALLOCATION AFTER
          ERROR LOGGING
%
-481,481,/,; DRS001/
/
```

RSX-11M V3.2
UTILITIES
BRUSeq 5.1.17.12 M
1 of 2

BRU TAPE LABEL PADDED WITH NULLS (SPR 11-30794 LK)

PROBLEM
STATEMENT

BRU didn't pad the tape label correctly in the ANSI VOL1 record when the tape label had less than 6 characters. This caused problems when BRU did a verify or compare operation or when we made an attempt to mount or dismount the tape.

RESPONSE

The following is a cumulative patch with .IDENT /01.2/ correcting the parsing algorithm.

Create the file [74,40]BRUPAR.PAT:

```
.TITLE BRUPAR
;
; COPYRIGHT (C) 1980
; DIGITAL EQUIPMENT CORPORATION, MAYNARD, MASS.
;
; MODIFICATIONS
;
;    01.1 - SET PROPER BIT FOR /WINDOWS QUALIFIER
;    01.2 - PUT BLANKS INTO THE LABEL FIELD
;
; .IDENT /01.1/
;
; .PSECT
; .BLK.=.
SETQ1=.BLK.+5470
; .WORD SETQ1      ; SET KEYWORD BIT IN THIS WORD
; .BLK.
```

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.12 M
2 of 2

```
.IDENT /01.2/
.PSECT
.MCALL DIR$  
.BLK.=.  
.=,BLK.+1662

CALL PAT1
NOP
.=.BLK.
.PSECT $SPAT
$SPAT=.

PAT1: MOV #SLAB,R1 ; PUT BLANKS INTO THE LABEL FIELD
      MOV #",,(R1)+  
      MOV #",,(R1)+  
      MOV #",,(R1)
      DIR$ #GETASK ; OBTAIN THE UIC WE ARE RUNNING UNDER
      RETURN
.END
```

Assemble BRUPAR.PAT to create BRUPAR.POB

```
>SET /UIC=[74,40]
>MAC BRUPAR.POB, BRUPAR=BRUPAR.PAT
```

Extract BRUPAR.OBJ from [1,20]BRU.DLB, apply the patch, assign TK:
to your target task build disk, and build BRU:

```
>LBR BRUPAR.OBJ;1=[1,20]BRU/EX:BRUPAR
>PAT BRUPAR.OBJ;2=BRUPAR.OBJ;1/CS:63056, BRUPAR.POB/CS:17051
>SET /UIC=[1,20]
>LBR BRU/RP=[74,40]BRUPAR.OBJ;2
>ASV ddn:=TK:
>TKB @[1,24]BRUBLD
```

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.13 M
1 of 5

/TAPELABEL DOESN'T WORK DURING RESTORE (SPR 11-32313 LK)

PROBLEM STATEMENT

The /TAPELABEL switch does not work during the restore operation from a tape.

RESPONSE

BRU does not check the input volume name during the restore operation from a tape. The following cumulative patch will correct this problem.

Create the file TAPEIO.PAT:

.TITLE TAPEIO

; COPYRIGHT (C) 1980
; DIGITAL EQUIPMENT CORP., MAYNARD, MASS.

; MODIFICATIONS:

01.1 --

CORRECT ERROR MSG IF TAPE DRIVER NOT LOADED

WAIT FOR DEVICE DETACHES TO AVOID EXIT WITH OUTSTANDING I/O

MAKE TAPEIO SERIALLY REUSABLE

CORRECT ERROR RETURN AT BOT FOR RESTORE

CORRECT "MOUNT TAPE" MESSAGE

CORRECT TAPE FORMAT IF NO FILES FOUND

01.2 --

INPUT TAPE LABEL VERIFICATION

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.13 M

2 of 5

```

; IDENT /01.1/
.MCALL DIRS,WTSESS
.PSELECT
.BLK.=.
; OUTPUT CORRECT MSG IF TAPE DRIVER NOT LOADED
.=.BLK.+36
BCS    158      ; HANDLER NOT RESIDENT
NOP
.=.BLK.+56
15$:
; WAIT FOR DETACHES TO COMPLETE
; MAKE TAPEIO SERIALLY REUSABLE
.=.BLK.+3570
CALL    PAT1      ; CALL PATCH
DIRS   #SDUDPB   ; DETACH THE OUTPUT DISK
BCS    30S       ; DON'T WAIT IF DETACH FAILS
WTSESS #EFN2     ; WAIT FOR OUTPUT DETACH
30$:   RETURN    ; DONE HERE
; CORRECT "MOUNT TAPE..." MESSAGE
CF.MES = 1000
.=.BLK.+1170
JMP    PAT2      ; JUMP TO PATCH
.REPT  6
NOP
.ENDR
.=.BLK.+1210
RWD1:::
.=.BLK.+1232
RWD2:::
.=.BLK.+1500
.REPT  3
NOP
.ENDR

```

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.13 M

3 of 5

```

.=.BLK.+1556
      BNE    380$          ; ZERO WAIT COUNT IF NO FILES FOUND

.=.BLK.+1640
      380$: .REPT 6          ; DATA OVERRUNS OCCURRED DUE TO
      NOP          ; IF SO REPEATEDLY
      .ENDR

.=.BLK.+2020
DIRDPB:
      LTRD, PAT TO SEARCH TAPE LOG PERIODICALLY
.=.BLK.+2042
      AUTOMATICALLY
      CMP    #IO.RWU, $TPDPB+0.IOFN ; RWU ISSUED?
      BNE    10$                 ; NO
      BIS    #CF.MES, SCFLAG   ; YES - NEED MOUNT TAPE MESSAGE
      10$:  MOV    #IO.SMO, $TPDPB+0.IOFN ; SET CHAR AND MOUNT FUNCTION
      20$:  CALL   DIRDPB        ; ISSUE DIRECTIVE
      TSTB   STPSTA           ; OK?
      BPL    40$                 ; YES - DONE HERE
      BIT    #CF.MES, SCFLAG   ; OUTPUT MESSAGE?
      BEQ    450$                ; NO
      TST    R0                 ; YES - NOW?
      BNE    450$                ; NO - TOO SOON
      BR     440$                ; YES
      40$:  BIC    #CF.MES, SCFLAG ; CLEAR FLAG
      RETURN

.=.BLK.+2142
      440$:

.=.BLK.+2176
      450$:
      50$:
      =.BLK.+2220
      BR     20$                ; TRY SMO AGAIN

CORRECT BOT ERROR RETURN FOR RESTORE
      =.BLK.+2572
      JMP    JPAT3              ; CHECK FOR CHANGES IN DIRECTORY
      CORRECT TAPE FORMAT IF NO FILES FOUND
      =.BLK.+3626
      20$:

```

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.13 M
4 of 5

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.13 M
5 of 5

```
CMP    $BUF2+10,SLAB+4      ; LAST COMPARE
BNE    150$                 ; READ UNTIL HDR1 ENCOUNTERED
20$:   CALL   READTP
WTSESS #EFN9
CMPB   $TPSTA,#IE.DAO      ; DATA OVERRUNS ARE BOOT BLOCKS
BEQ    20$                 ; IF SO KEEP GOING
RETURN
150$:  TST    (SP)+          ; ADJUST STACK
JMP    POPA
```

.END

Assemble TAPEIO.PAT to create TAPEIO.POB:

```
>SET /UIC=[74,40]
>MAC TAPEIO.POB,TAPEIO=TAPEIO.PAT
```

Extract the module TAPEIO.OBJ;1 from the library [1,20]BRU.OLB; apply the patch, assign your target task build output disk to TK: and rebuild BRU.

```
>LBR TAPEIO.OBJ;1=[1,20]BRU.OLB/EX:TAPEIO
>PAT TAPEIO.OBJ;2=TAPEIO.OBJ;1/CS:113475,TAPEIO.POB/CS:161254
>SET /UIC=[1,20]
>LBR BRU/RP=[74,40]TAPIO.OBJ;2
>ASN ddn:=TK:
>TKB @[1,20]BRUBLD
```

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.14 M

1 of 5

BRU HANGS OR CREATES AN INCORRECT INDEX FILE BITMAP (SPR 11-31026 DD)

PROBLEM STATEMENT

BRU may hang when transferring a very large contiguous file, or may create an incorrect index file bitmap on the output volume.

RESPONSE

The following is a cumulative patch for the file BRUHEAD.OBJ. The above problems are corrected by the patches with .IDENT /01.7/ and /01.8/. When submitting any BRU SPRs, an LPR listing (LBR BRU.OLB/FU) should be included to show the patch level of BRU modules.

Create the file BRUHEAD-PAT:

.TITLE BRUHEAD

COPYRIGHT (C) 1979, 1980

DIGITAL EQUIPMENT CORPORATION, MAYNARD, MASS. 01754

MODIFICATIONS

01.1 - CORRECT CONTIGUOUS FILE ALLOCATION
01.2 - RESTORE FULL FILE ATTRIBUTES WHEN TRANS
 MOUNTED DISK
01.3 - FIX SEQUENCE NUMBER ON EXTENSION HEADER
01.4 - FIX CREATION OF EXTENSION HEADERS

SUPERSEDES 01.4 WITH INCORRECT PLACEMENT OF SS

01.5 - FIX RESTORE OF MULTIHEADER FILES TO A M

01.6 - FIX CREATION OF EXTENSION HEADERS
01.7 - FIX INDEX FILE BITMAP INITIALIZATION
01.8 - FIX RESTORE OF LARGE CONTIGUOUS FILES

.IDENT /01.1/

RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.14 M
2 of 5

```
.PSECT
.BLK.=.
CONDSP=.BLK.+106
.=.BLK.+6112
    CALL    PAT1 ; CALL PATCH
.=.BLK.

.PSECT  $SPAT
$SPAT=.
PAT1: SUB    #2,CONDSP ; CHECK DISPLACEMENT
      RETURN
      .IDENT /01.2/
      .MCALL FHDOFS
      FHDOFS
      SIDTOF =      56 ; DEFINE FILE HEADER OFFSETS
                        ; FILE HEADER IDENT AREA WORD OFFSET
.PSECT
.BLK.=.
.=.BLK.+3312
      MOV    #RSATR,SODPB+Q.IOPL+2 ; SET UP WRITE ATTRIBUTE DPB
      MOV    #SIDTOF+I.RVNO,RSATR+2 ; WANT TO CORRECT REVISION DATE
      CALL   PAT2 ; CALL PATCH TO SET UP MORE ATTRIBUTES
.=.BLK.

.PSECT  $SPAT
$SPAT=.
PAT2: ADD    R5,RSATR+2 ; MAKE DATE ADDRESS ABSOLUTE
      MOV    #H.UFAT,RSATR+6 ; WRITE RECORD I/O AREA TOO
      ADD    R5,RSATR+6 ; MAKE RECORD I/O AREA ADDRESS ABSOLUTE
      RETURN
RSATR: .BYTE  13,,35. ; WRITE TIME/DATE ATTRIBUTES
      .WORD   0 ; TIME/DAT ADDRESS (DONE AT RUNTIME)
      .BYTE  4,32. ; WRITE RECORD I/O AREA
      .WORD   0 ; RECORD I/O AREA ADDRESS (DONE AT RUNTIME)
      .WORD   0 ; ZERO TO TERMINATE ATTRIBUTE LIST
      .IDENT /01.3/
```

RSX-11M V3.2
UTILITIES
BRUSeq 5.1.17.14 M
3 of 5

```

.PSECT
.BLK.=.BLK.+166
SENUM=.BLK.+166
.=.BLK.+3626
    CALL    PAT3      ; CALL PATCH TO SET SEQUENCE # IN NEW HEADER
.=.BLK.

.PSECT SSPAT
$SPAT=.
PAT3: ADD    #M.USC-M.FSQN,R2 ; POINT BACK TO RP USE FIELD
      MOV    SENUM,H.FSEQ(R0) ; SAVE SEQUENCE NUMBER IN HEADER
      RETURN
.IDENT /01.4/
.PSECT
.BLK.=.BLK.+102
NRPCNT=.BLK.+102
.=.BLK.+2054
    RORB    NRPCNT      ; ALSO FIX NEW RP COUNT FOR NEXT TIME
.=.BLK.

.IDENT /01.5/
.PSECT
.BLK.=.BLK.+1460
.=.BLK.+2064
    BIT    #RS.SYN!RS.MOU,SRSFLG ; FILE SYNONYM OR MOUNTED DISK?
    BIT    #RS.CMP!RS.SYN!RS.MOU,$RSFLG ; TOY WITH EXTENSION HEADERS?
.=.BLK.

.IDENT /01.6/
.PSECT
.MAPPTR=.BLK.+204

```

RSX-11M V3.2
UTILITIES
BRUSeq 5.1.17.14 M
4 of 5

```

.=.BLK.+11252          TOT34.
    NOP
    CALL    PAT4           ; CALL PATCH TO SET UP MAP AREA POINTER

.=.BLK.          2          2
    .PSECT  $$PAT          2
    $$PAT=.
        $MAPOF =      134   ; MAP AREA WORD OFFSET
        PAT4: MOV      R0,MAPPTR ; RESET THE POINTER TO THE RP MAP AREA
        ADD      #$MAPOF+M.RTRV-M.ESON,MAPPTR ;
        RETURN
    .IDENT /01.7/
    .PSECT
.=.BLK.=.
    .BLK.+632          0          ; SHOW FIRST FITMAP BLOCK IN BUFFER
    .WORD
.=.BLK.          0
    .IDENT /01.8/
    .PSECT
.=.BLK.=.
    XSGNUM=.BLK.+103
    .BLK.+1120          0          ; CALL PATCH TO SAVE TOTAL FILE SIZE
    CALL    PAT5           ; CALL PATCH TO SAVE TOTAL FILE SIZE
    .BLK.+1564          0          ; GET ALLOCATION SIZE FROM 1ST HEADER
    MOV     TOTSIZ,$ALLSZ ; GET ALLOCATION SIZE FROM 1ST HEADER
    MOV     TOTSIZ+2,$ALLSZ+2 ; THIS PRESENTS THE ENTIRE FILE SIZE
    .BLK.          0
    .PSECT  $$PAT          0
    $$PAT=.
    PAT5:   MOV     H.UFAT+F.HIRK(R0),TOTSIZ ; SAVE TOTAL SIZE OF FILE
    MOV     H.UFAT+F.HIRK+2(R0),TOTSIZ+2 ; FOR POSSIBLE USE LATER
    CLR8   XSGNUM          ; RESET EXTENSION SEGMENT NUMBER
    RETURN

```

M
RSX-11M V3.2
UTILITIES
BRU

Seq 5.1.17.14 M
5 of 5

TOTSIZ: .BLKW 2 ; TOTAL SIZE OF FILE (# OF BLOCKS)
.END

Assemble BRUHEAD.PAT to create BRUHEAD.POBI.

```
>SET /UIC=[74,40]
>MAC BRUHEAD.POBI=BRUHEAD.PAT
```

Extract the module BRUHEAD.OBJ from [1,20]BRU.OLB, apply the patch,
assign TK: to your target output device, and build BRU.

```
>LBR BRUHEAD.OBJ;1=[1,20]BRU/EX:BRUHEAD
>PAT BRUHEAD.OBJ;2=BRUHEAD.OBJ;1/CS:27167, BRUHEAD.POBI/CS:72337
>SET /UIC=[1,20]
>LBR BRU/RP=[74,40]BRUHEAD.OBJ;2
>ASN ddn:=TK:
>TKR @[1,24]BRUBLD
```

RSX-11M V3.2
MISC SYSTEM TASKS
RMD

Seq 5.7.5.3 F

1 of 3

A WAY TO REDUCE OVERHEAD IN RMD (SPR 11-80028Z AG)

PROBLEM STATEMENT

RMD updates the screen 1 line at a time. This means that it can take up to 24 QIO's to update. Most of these QIO's are relatively small, making the overhead to update the screen excessive.

RESPONSE

The following patch, when applied to module RMDRIV will make RMD fill a 256 buffer before issuing a QIO. This means that, after the original screen paint, the screen can almost always be updated with a single QIO. This has resulted in a significant reduction in system overhead.

```
OU:RMDRIV.MAC:2/AU/-BF=IN:[14,10]RMDRIV.MAC;1
\
-2,2
    .IDENT /1.2/
-9,9
; VERSION:      1.2
-11
; MODIFICATIONS:
;
;      AG046  CHANGE TO SINGLE LONG QIO
;
% -33,33,;/AG046/
    .MCALL QIOWS,DIRS,*SIGSS,WTSESS
-49,,;/AG046/
;
        ."ACRO  PUTC    CHAR,?A          ; PUT CHARACTER TO OUTPUT BUFFER
        CYP    R5,#BUFFER+RUFL-1
        BLT    A
        CALL   OUTPUT
        A:     MOVB   CHAR,(R5)+
        .ENDM
```

EWOLLET ZA BILDEY EHS ALDNEASST. HEDP. DNE 0227. NALDNEASST. ZIT. VITA
EADY

RSX-11M V3.2
MISC SYSTEM TASKS
RMD

Seq 5.7.5.3 F
3 of 3

```
SET /UIC=[14,24]
MAC RMDRIV,[14,34]RMDRIV/-SP=[1,1]EXEMC/ML,[11,10]RSXMC/PA:1,[14,10]RMDRIV
SET /UIC=[1,24]
LBR RMD/RP/-EP=[14,24]RMDRIV
```

TKB @RMDBLD

RSX-11M V3.2
DRIVERS
FDX-TTDRV

RSX-11M/S - RSX-11M-PLUS Software Dispatch, September 1980

Seq 3.1.3.9 N
DRIVERS
FDX-TTDRV
1 of 2

FULL DUPLEX TERMINAL DRIVER QUESTIONS ANSWERED (SPR 11-80029Z DD)

The following is a compilation of answers to often asked questions about the Full Duplex Terminal Driver. These procedures are provided for information only and are unsupported.

Q1: How do I select the size of the driver's partition, called TTPAR in RSX-11M systems, or TTCOM for RSX-11M-PLUS systems?

A1: By default, SYSGEN sets the size of TTPAR (TTCOM) to 8K words, but it can usually be made smaller. TTPAR contains code plus a private buffer pool, which is allocated in 20 word chunks for typeahead buffers, UCB extensions, and I/O buffers. Since the amount of I/O buffers required depends on both system activity and the length of the I/O requests, an exact sizing guideline cannot be given. A rough algorithm for determining the size of TTPAR is:

$$P = C + (20 * T) + (60 * A)$$

Where:
 C is the code size of the driver (from the line "TASK IMAGE SIZE" in [1,34]TTDRV,MAP)
 T is the number of terminals in the system
 A is the average number of I/O requests pending at any time

The above formula can be used to determine the size of TTCOM for RSX-11M-PLUS systems by setting C = 0 (since the code is strictly Instruction space and TTCOM is strictly Data space).

The value obtained for P is in decimal words; convert to octal bytes/100(8) for the TTPAR SET /MAIN command. For M-PLUS systems, convert P to octal words and use the result as the argument for the /SIZE switch of the VMR LOAD command.

If space is exhausted in TTPAR (TTCOM), the terminal driver will attempt to use primary pool, so if you're short on system pool, pad TTPAR (TTCOM) for comfort.

NOTE: The following answers involve changing code within the driver. It is recommended that a correction file be created to apply the changes stated, although it is possible to make the changes with ZAP or OPEN. The line numbers cited refer to version 1 of the appropriate module. All the modules reside in [11,10].

RSX-11M V3.2
DRIVERS
FDX-TTDRV

Seq 3.1.3.9 N

2 of 2

- Q2: The Full Duplex Terminal Driver will attempt to buffer both input and output requests to allow the task to be checkpointed. How do I disable this feature if it is causing thrashing in my system?
- A2: The driver stops a task while it performs terminal I/O. Checkpointing will occur only if there is contention for the memory the I/O bound task occupies. Thrashing between many tasks performing terminal I/O can occur and will degrade system response due to excessive checkpointing, especially if the I/O requests are for single characters. To disable stopping and checkpointing a task performing terminal input, change line 134 of the module TTRW.MAC which reads:
- ```
 BCS UNBI ;N = JUMP ;DISALLOW CHECKPOINTING DURING INPUT
```
- To disable stopping and checkpointing a task performing terminal output, change line 811 of the module TTRW.MAC which reads:
- ```
        BCS    CLR16   ;N = JUMP ;DISALLOW CHECKPOINTING DURING OUTPUT
```
- Note that a read with prompt function is considered an output request when the check for buffering is made.
- Q3: When a remote (dial-up) line is answered, the characteristics of the line are reset and the speed is changed to a rate specified at SYSGEN. How can I disable the resetting of the line characteristics and baud rate?
- A3: The resetting of the line characteristics is done by routine MANS in the module TTMOD.MAC (line 167). To maintain the line parameters across dial-ins or to reset them to a particular setting, modify lines 167 through 178 appropriately. Note that this routine returns the C-bit clear, so make sure that any local modifications adhere to this. Also note that line 173 is where the speed is reset. This line should be commented out (place a semi-colon before it) to not affect the baud rate. In addition, to maintain the baud rate constant, the following line should also be commented out:
- If your remote lines are interfaced through a DH-11, comment out line 594 of the module TTYH.MAC, which reads:
- ```
 MOV T$8MAN,LPR(R3) ;SET LINE PARAMETERS
```
- If your remote lines are interfaced through a DZ-11, comment out line 190 of the module TTYZ.MAC, which reads:
- ```
        MOV    @SP,LPR(R3) ;LOAD PARAMETERS
```

RSX-11M V3.2
DRIVERS
FDX-TTDRV

Seq 3.1.3.1g N
1 of 1

NOTE ON USING TERMINAL DRIVER SUBFUNCTION TF.RCU (SPR 11-26495 DD)

PROBLEM
STATEMENT

Terminal Driver subfunction TF.RCU does not work as described in the manual.

RESPONSE

Note that the restore cursor position subfunction (TF.RCU) will only work correctly if the terminal driver knows the exact position of the cursor. Although the driver attempts to accurately maintain the cursor co-ordinates, it is not always possible to accomplish this. For example, if a task outputs a cursor positioning escape sequence, the driver cannot interpret the sequence to track the new cursor location. Write-pass-all output is not tracked at all. In addition, turning a terminal off and on may reset the cursor to home position without the driver's knowledge. Before using the TF.RCU subfunction, to get back into synchronization, it is therefore best to use the driver's cursor positioning feature (via the VFC parameter) to set both the terminal and driver cursor co-ordinates to a fixed location.

RSX-11M V3.2
RSX-11M-PLUS V1.0
IAS V3.0
FORTRAN IV V2.2

1 of 1

LINKING FCSRES TO FORRES OR F4PRES

Fortran and Fortran IV-PLUS users who want to reduce the size of their respective resident libraries can do so by linking either FORRES or F4PRES to FCSRES (File Control Services Resident Library).

In order to link either resident library to FCSRES the user must first allocate enough space at task build time to allow FCSRES to be mapped. To do this the user must specify a lower base address for the FORTRAN or FORTRAN IV-PLUS resident library than would be normally specified if no linking to FCSRES was going to be done. The base address to be used will vary depending on the size of FCSRES but if the size of FORRES or F4PRES is 8K words and the size of FCSRES is 4K words the base address used at task build time will be 120000 instead of the normal 140000. The size of either FORRES or F4PRES should be the same (ie. 40000).

The following example shows how to build a FORTRAN IV V2.2 resident library:

```
>MAC FORRES,FORRES/-SP=FORRES    #ASSEMBLE FORRES
>TKB
TKB>[1,1]FORRES/-HD/-PI,FORRES/-SP-[1,1]FORRES=FORRES,E1,1]FORROT3/LB
TKB>/
ENTER OPTIONS:
TKB>STACK=0
TKB>PAR=FORRES:120000:40000
TKB>LIBR=FCSRES:RO
TKB>//
```

ASSUMPTIONS :

FORRES is 8K words.

FCSRES is 4k words.

FCSRES was already created and installed.

The Small Buffer, Volume 527, 1 May 1980

RSX-11M V3.2

JOHN L. HENNING, WPS DEVELOPMENT, CENTRAL COMMERCIAL ENGINEERING, MK1-2/G1Ø

1 of 2

SAVING MEMORY UNDER RSX-11M V3.2

Only two PDP-11s support memory sizes greater than 124K words: the 11/44, and the 11/70. Since RSX-11M-PLUS is the natural choice on the 44 and 70, most use of RSX-11M should be on machines which have relatively small amounts of memory. Unfortunately, the default RSX-11M V3.2 Sysgen options do not make optimal use of memory on small systems.

Do the following to tailor an RSX-11M V3.2 system to a memory-limited machine:

1. SYSVMR.CMD sets the size of POOL to the maximum. If you don't need that much, change it.
2. For systems with the full duplex terminal driver, SYSVMR sets TTPAR to 8K words, but it can usually be made much smaller. TTPAR contains code plus a private buffer pool, which is allocated in 20 word chunks for type-ahead buffers, UCB extensions, and i/o-pending buffers. Since the space needed for the i/o-pending buffers depends on both system activity and the sizes of the i/o requests, an exact sizing guideline cannot be given. A rough guideline for sizing TTPAR is:

$$P = C + (20 * T) + (60 * A)$$

Where P is the size of TTPAR in decimal words
C is the code size (from the line "TASK IMAGE
SIZE" in [1,34]TTDRV.MAP)
T is the number of terminals in the system
A is the number of users likely to be ACTIVELY
typing at one time

The value obtained for P is in decimal words; convert to octal bytes/100 for the TTPAR SET /MAIN command. If space is exhausted in TTPAR, the driver will attempt to use the system pool, so if you're short on system pool, pad TTPAR for comfort.

The Small Buffer, Volume 527, 1 May 1980

RSX-11M V3.2

JOHN L. HENNING, WPS DEVELOPMENT, CENTRAL COMMERCIAL ENGINEERING, MK1-2/G10

2 of 2

3. SYSVMR.CMD allocates space in DRVPAR for ALL loadable drivers selected. If you don't need all of them all of the time, don't load them in VMR and don't allocate space for them in DRVPAR (thereby saving both memory and pool). Instead, use the MCR command LOAd as needed. Use /HIGH and /PAR to avoid memory fragmentation -- for example,

LOA DX:/PAR=GEN/HIGH

CAUTION: Memory fragmentation can be a worse problem than wasted memory. Loading on an as-needed basis is helpful only if both the following conditions are met: 1) The driver is not needed very often; 2) The users who issue the LOAD command know how to avoid fragmentation--i.e. they've read the documentation of the LOAD command, understand /HIGH and /PAR, and know how to run RMDEMO.

4. As described in the Software Dispatch issue of March, 1980, the queue manager system can be reduced from 32K words to just over 12K words by rebuilding without the PAR task builder directives. Or, you can achieve the same effect by REMoving the tasks and re-INStalling with /INC=0.
5. COT... and ...RMD, too, are built to an over-large 8K words. Remove and install with zero increment.
6. If VT52 support is all that is needed for an RMDEMO program, the old RMD52 from version 3.1 is adequate. Retrieve it from a V3.1 kit, and re-build under V3.2, to yield a 1.5K word task. Since RMD52 doesn't have all the features of the new program, we keep both versions on our system: RMD52 installed as ...RMD, and the version 3.2 RMDEMO installed as RMDBIG. Of course, use of the old V3.1 RMDEMO program under V3.2 is UNSUPPORTED.