

TAB - generic TAB, 12 mod 3A
 SPACE - hot ERASE CHAR
 LED 3 - Message waiting
 LED 4 - Wait

PF1 F1	PF2 F2	PF3 F3	PF4 F4
7 Erase unprot.	8 Erase to eol	9 Erase field	- Erase display
4 Delete in line	5 Insert in line	6 Cursor home	Unlock keyboard
1 Message waiting	2 Repaint screen	3 Help	ENTER Transmit unprot display
0 SOE		TAB	

L3 Processor message waiting ('Message waiting')
 L4 Keyboard locked ('Wait')

esc E	Delete line	esc F	Insert line
esc G	Delete in display	esc H	Insert in display
esc I	Blink on	esc J	Blink off
esc K	Hard copy print	esc L	Output to auxiliary device
esc N	Input from auxiliary	esc X	Transmit display

TAB, Set tabulator SPACE Erase character